## **Cleanup Site Details**

9/7/2015

		^=	~~	111171
М	IEK	CE	CO	UNTY

SITE ID:	ALADDIN PLATING CO INC		Clea	nup Site ID: 3257	FS ID: 1277		
	Alternate Name(s): ALADDIN PLATING CO INC						
LOCATION:		WRIA: 10	Lat/Long:	47.234	-122.457	View Vicinity Map	
Address:	1657 CENTER ST			Township	Range	Section	Legislative District: 27
	TACOMA	98409-7919		20N	3E	8	Congressional District: 6
STATUS:	Cleanup Started		Rank: 2		<u>View Site Web Page</u>		View Site Documents
	Responsible Unit: Southwest	Site Manager:	Site Manager: Kourehdar, Mohsen		Statute: MTCA		
	Is Brownfield?	Has Enviro	Has Environmental Covenant?  NFA Date:		Is PSI Site?		
	NFA Received?	NFA Date:					

### ASSOCIATED CLEANUP UNIT(s)

cuID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
783	ALADDIN PLATING CO INC	Upland	Ecology-supervised or conducted	Cleanup Started		

#### SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	2/10/1995	6/29/1995		Ecology	Southwest Region
CleanupSite		Hazardous Sites Listing/NPL			8/22/1995			Southwest Region
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasilibity Study	Canceled	10/20/2002		Governmental Action	Ecology w/ Contractor	Kourehdar, Mohsen
CleanupSite		Ecology Cleanup Construction	Canceled	1/2/2005	7/1/2005		Ecology w/ Contractor	Kourehdar, Mohsen

#### AFFECTED MEDIA & CONTAMINANTS:

#### Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Metals - Other	S		S			
Metals Priority Pollutants	S		С			

- Key:
  B Below Cleanup Level
  C Confirmed Above Cleanup Level
- S Suspected

- R Remediated
- RA Remediated-Above
- RB Remediated-Below



# Cleanup Site Details

9/7/2015

CleanupSiteDetails2014